



STEERING COLUMN SWITCH TECHNICAL INFORMATION 440460



GENERAL INFORMATION

For a proper parameter reset, an updated professional auto diagnostic equipment is recommended.

If this equipment is not available, if the error signal is still on and if the parameters are not updated with the ECU, a contact with the local authorized dealer is recommended.